

कार्यालय
अनुविभागीय अधिकारी
लोक निर्माण विभाग, पश्चिम उपसंभाग
भोपाल, म० प्र०

क्रमांक 506 / सहा. अनु. लि. / 2016

भोपाल, दिनांक 24-10-16

To,
The Manager
Sagar Public School
9A Saket Nagar,
Bhopal


Reference: - Your letter No. Nil dated 19/10/2016
Subject: - Checking of the Structural Integrity of the School Building.

Sir,

With reference to the aforesaid please note that the design documents and drawings of the construction of your school building at Sagar Public School, 9A Saket Nagar Tehsil Hujur District Bhopal have been reviewed and the rapid visual survey of the said building was conducted on 22/10/2016.

Based on the review of the documents and the Visual Survey of the building it can be certified the design and the construction of the building is as per the prevailing codes of practice and the building is well designed to sustain the gravity loads as per the Indian standard codes of Practice.

The visual observations we do not take the responsibility of any changes / errors during construction.


(R.P.Gupta)

Sub-Divisional Officer
P.W.D. West Sub-Division, BHOPAL

Sub Divisional officer
P.W.D West Sub- Division, Bhopal